# Oil Field Environmental Incident Summary

**Responsible Party:** ENDURO OPERATING, LLC **Well Operator:** ENDURO OPERATING, LLC

Well Name: FEDERAL RIVET 6-3 SWD

Field Name: PIERRE CREEK Well File #: 11729

Date Incident:6/1/2014Time Incident:08:40Facility ID Number:County:MCKENZIETwp:146Rng:102Sec:6Qtr:

**Location Description:** 

Submitted By: Rodney Conway Received By:

Contact Person: Rodney Conway

777 MAIN STREET

SUITE 800

FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:2 MileDistance Nearest Water Well:2 Mile

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Reco	vered Units	F	ollowup	Units
Oil	5	Barrels	5	Barrels		5	barrels
Brine	20	Barrels	18	8 Barrels		18	barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 10/6/2015 Clean Up Concluded: 6/5/2014

Risk Evaluation:

none

Areal Extent:

Just offf lease a small amount. BLM there for cleanup requirements.

## Potential Environmental Impacts:

none

# Action Taken or Planned:

All valves were plugged and fence to be repaired or replacedwhere needed.

Wastes Disposal Location: Indian Hill land disposal when possible. Cleaning upnd putting soil on a paltic liner untill shiiped to land fill.

Agencies Involved:

## **Updates**

Date: 6/4/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

According to the spill report, the release was not completely contained on location. However, BLM operator was on location and dictated cleanup requirements, according to the report